

Name of Product: DEWALT Cordless Drills

Units: About 346,000

Manufacturer: DEWALT Industrial Tool Company, of Towson, Md.

Hazard: The trigger switch of the cordless drill can overheat, posing a fire hazard to consumers.

Incidents/Injuries: DEWALT has received 11 reports of trigger switches overheating. No injuries or property damage have been reported.

Description: This recall involves DEWALT individual cordless drills listed below:

Model Number: DC920

Heavy-Duty XRP(tm) 1/2" (13mm) 18 Volt Cordless Drill/Driver

200723 through 200742

DC930

Heavy-Duty XRP(tm) 1/2" (13mm) 14.4 Volt Cordless Drill/Driver

200625 through 200746

DC935

Heavy-Duty XRP(tm) 1/2" (13mm) 14.4 Volt Cordless Hammerdrill/Drill/Driver

200627 through 200746

DC936

Heavy-Duty XRP(tm) 1/2" (13mm) 14.4 Volt Cordless Hammerdrill/Drill/Driver

200635 through 200746

DC940

Heavy-Duty XRP(tm) 1/2" (13mm) 12 Volt Cordless Drill/Driver

200635 through 200746

The model number is printed on a sticker on the side of the unit. The date code is embossed on the bottom of the unit. Units stamped with an "M" following the date code have been repaired and are not included in this recall. The packaging of repaired drills has a green dot sticker near the UPC label.

Sold at: Wholesale distributors and retailers from about June 2006 through December 2007 for between \$180 and \$280.

Manufactured in: Mexico

Remedy: Consumers should stop using the drills immediately and contact DEWALT for the location of the nearest service center to receive a free inspection and, if necessary, free repair.

Consumer Contact: Call DEWALT toll-free at (888) 742-9168 between 8 a.m. and 5 p.m. ET Monday through Friday or visit firm's Web site at <http://www.dewalt.com/us/core/> or visit the [CPSC Recall page](#).