

**Name of Products: Honda Walk-Behind Lawn Mowers**

Units: About 167,000

Manufacturer: American Honda Motor Corp., of Torrance, Calif.

Hazard: The cutting blades could rotate under power when the control lever is released. The lawn mowers do not comply with mandatory federal safety standards for lawn mowers. The spinning blade poses a serious laceration hazard to consumers.

Incidents/Injuries: None reported.

Description: The recall involves Honda walk-behind lawn mowers with model numbers HRB217HXA, HRX217HXA and HRX217HMA. The model and serial number are printed on a label located on the upper rear of the mower deck. The lawn mowers are dark gray with a red fan cover. The following serial numbers are included in the recall:

Model HRB217HXA: All Serial Numbers .Models HRX217HXA and HRX217HMA: Serial Numbers 1000001 - 1513628

Sold by: Honda Lawn and Garden dealers and The Home Depot stores nationwide from January 2003 through November 2007 for between \$760 and \$900.

Manufactured in: United States

Remedy: Consumers should stop using these recalled lawn mowers immediately and contact any Honda Lawn and Garden dealer for a free repair. Registered owners will be mailed a direct notice.

Consumer Contact: For additional information, contact Honda at (800)426-7701 between 8:30 a.m. and 5 p.m. ET Monday through Friday, or visit the firm's Web site at <http://www.hondapowerequipment.com/> or the [CPSC Recall page](#).