

Manufacturer: Ryobi Motor Products Corp.

Home and hardware stores nationwide from 1986 through 1997 for between \$200 and \$300. Cracking of the plastic motor housing can cause the blade assembly to fall during operation, posing a risk of laceration to the operator or bystanders. The detachment may occur unexpectedly and without warning. Contact Ryobi Customer Service at (800) 525-2579 between 8 a.m. and 4 p.m. ET any day of the week, or [visit the recall site](#).