

Manufacturer: Tele-motive

Model: Series 8000. It is urgent that the Remote Control Crane Box mentioned above be inspected for loose screws from the battery compartment. In investigation of a recent accident involving a Steelworkers member, a loose screw was discovered, which had stuck to adhesive mylar tape in the box. The screw had lodged in the micro switch and may have caused unexpected crane movement. Inventory your workplace to see if this box is being used or in stock.

If this box is in your location:

- you should inspect all boxes immediately
- include the box in your crane inspection program
- contact the manufacturer for any updates or design modifications

