

Manufacturer: Robert Bosch Tool Corp., Mount Prospect, IL

Model: BOSCH CS10, CS20 AND CS20-XC CPSC and Robert Bosch announced recall, 5/18/2005. The lower blade guard can malfunction, creating a risk of injury as severe as amputation. Consumer should stop using the circular saws immediately and contact Robert Bosch Tool Corp. to receive a repair kit. The kit includes hardware and instructions for installation. Contact: Robert Bosch Tool Corp. at (800) 856-9683 between 7 a.m. and 7 p.m. CT Monday through Friday or visit the [BOSCH Web site](#) to [view recall](#).